



داریانا افغان هوایی شرکت
ARIANA AFGHAN AIRLINES

Borescope Inspection Result Form

ENGINE TYPE	A/C	Eng. SN	POS	TSN	CSN	PLACE
CFM56-3C1		857581		52092:00	32617	KBL
Reason BSI						

LPC (booster)	Sub_Ref	AMM 72-00-00-216-008-C00			
	Rev_No		Rev. Date	25 Mar 2023	
Remarks:					
NO SIGNIFICANT DEFECT NOTED.					

HPC	Sub_Ref	AMM 72-00-00-216-049-C00			
	Rev_No		Rev. Date	25 Mar 2023	
Remarks:					
NO SIGNIFICANT DEFECT NOTED.					

CC & NGVs	Sub_Ref	AMM 72-00-00-216-023-C00			
	Rev_No		Rev. Date	25 Mar 2023	
Remarks:					
NO SIGNIFICANT DEFECT NOTED.					

HPT Turbine	Sub_Ref	AMM 72-00-00-216-026-C00			
	Rev_No		Rev. Date	25 Mar 2023	
Remarks:					
NO SIGNIFICANT DEFECT NOTED.					

LPT blades	Sub_Ref	AMM 72-00-00-216-045-C00 (stg 1,2,3) 72-00-00-726-050-C00 (stg 4)			
	Rev_No		Rev. Date	25 Mar 2023	
Remarks:					
NO SIGNIFICANT DEFECT NOTED					

If hand cranking cover is removed, hand cranking must be installed			Performed by	Inspected by
			Ab.Wahid F	Ahmad Sair Rahat
Inspected Date:	26/07/2025	Signature		
Engine Condition	DUE TO LLP	Stamp		