

Borescope Inspection Result Form

ENGINE TYPE	A/C	Eng. SN	POS	TSN	CSN	PLACE
CF6-80C2A2		695301		71976:05	26018	KBL
Reason BSI						

LPC (booster)	Sub_Ref	AMM 72-00-00)-216-008-C00
	Rev_No	Rev. Date	25 Mar 2020
Remarks:			
NO SIGNIFICA	NT DEFECT NO	OTED.	

HPC	Sub Ref	AMM 72-00-00	0-216-049-C00
	Rev No	Rev. Date	25 Mar 2021
Remarks:			
NO SIGNII	FICANT DEFECT NO	OTED.	

CC & NGVs	Sub Ref	AMM 72-00-00	0-216-023-C00
	Rev_No	Rev. Date	25 Mar 2021
Remarks:			
SOME NGVs	WITH BURNS V	VITHIN LIMIT.	
CC SOME AR	EAS WITH BU	RNS WITHIN LIMIT	•

HPT Turbine	Sub_Ref	AMM 72-00-00	0-216-026-C00
	Rev_No	Rev. Date	25 Mar 2020
Remarks:			
HPT FRIST ST	AGE A BOUT FI	VE BLADES HAVE M	IISSIING METERIAL AT
THE TIP ARIA			

LPT blades	Sub Ref		AMM 72-00-00-216-045-C00 (stg 1,2,3)		
		72-00-00-726-050-C00 (stg 4)			
	Rev_No	Rev. Date	25 Mar 2022		
Remarks:					
NO SIGNIFIC	ANT DEFECT NO	OTED			

If hand cranking cover is removed, hand cranking must be installed			Performed by	Inspected by
			Ab. Wahid F	Ahmad Sair Rahat
Inspected Date:	11.12.2024	Signature	443	82
Engine	Serviceable	Stamp	\$200	(TNM
Condition			(by a	