

## Borescope Inspection Result Form

ENGINE TYPE	A/C	Eng. SN	POS	TSN	CSN	PLACE
CFM56-3C1		858979		48580:48	34329	KBL
Reason BSI						

LPC (booster)	Sub_Ref	AMM 72-00-00-216-008-C00	
	Rev_No	Rev. Date	25 Mar 2023
Remarks:			
NO SIGNIFICANT DEFECT NOTED.			

HPC	Sub_Ref	AMM 72-00-00-216-049-C00	
	Rev_No	Rev. Date	25 Mar 2023
Remarks:			
NO SIGNIFICANT DEFECT NOTED.			

CC & NGVs	Sub_Ref	AMM 72-00-00-216-023-C00	
	Rev_No	Rev. Date	25 Mar 2023
Remarks:			
SOME NGVs WITH BURNS WITHIN LIMIT. CC SOME AREAS WITH BURNS AND CRACKS .			

HPT Turbine	Sub_Ref	AMM 72-00-00-216-026-C00	
	Rev_No	Rev. Date	25 Mar 2023
Remarks:			
HPT FRIST STAGE A SOME BLADES HAVE MISSIING METERIAL AT THE TIP ARIA.			

LPT blades	Sub_Ref	AMM 72-00-00-216-045-C00 (stg 1,2,3) 72-00-00-726-050-C00 (stg 4)	
	Rev_No	Rev. Date	25 Mar 2023
Remarks:			
NO SIGNIFICANT DEFECT NOTED			

If hand cranking cover is removed, hand cranking must be installed		Performed by	Inspected by
		Ab.Wahid.F	Ahmad Sair Rahat
Inspected Date:	26/07/2025	Signature	
Engine Condition	DUE TO LLP	Stamp	

